

## 2007-8 Annual Visual Inspection

1. School District: Lindenhurst 2. SED Control #: 5801040300000002  
3. Building Name: Lindenhurst Middle School 4. SED District #: 58010403  
5. Survey Inspect. Date: 8/22/2007 6. Building 911 Address: 350 S. Wellwood Avenue  
7. City: Lindenhurst 8. Zip: 11757 9.&10. C/O Status: CURRENT 08/01/08

### Building Age and Gross Square Footage

11. Yr. Original Building: 1932 12. Gross Sq.FT as Configured: 186407  
13. Number of Floors: 3

### Building Ownership and Occupancy Status

14. Building Use Status (Disposition as of 10/01/07): a.Occupied  
15. Building Ownership: a.Owned  
16. Purposes Building is Currently Used?:  
 Student Instructional Purposes  Other Purposes: \_\_\_\_\_  
 District Administration  Used by Other Organizations

### Building Users

17. Students registered to receive instruction in this building as of 10/1/07: 1692  
18. Of these, how many receive most of their instruction in:  
Permanent Instructional Spaces: 1692 Temporary Instructional Spaces: 0  
Non-instructional Spaces used as Instructional Spaces: 0  
 Cafeteria  Library  Storage Space  
 Gym  Lobby  Other (Describe): \_\_\_\_\_  
 Admin. Spaces  Stairwell  
19. Grades Housed: 6-8 20. Days Building Closed for '06-'07: 0  
 21. Building used for instructional purposes in the summer?  
 22. Renovations or construction during past 12 months?

### Program Spaces

23. Number of General Purpose Classrooms: 87  
24. Gross Sq. FT of all Gen. Purpose Classrooms: 78300



Site Storm Drainage:

40a. Quality of drainage: Good \_\_\_\_\_

40b. Cost to reconstruct/replace: \$0.00 \_\_\_\_\_

40c. Comments: \_\_\_\_\_

Site Electrical, incl. Exterior Dist.:

41a. Utility Provide  Self Generate  Other 41b. Type of service: Below Ground \_\_\_\_\_

41c. Condition: Satisfactory 41d. Year of last reconstruct/replace: 2001 \_\_\_\_\_

41e. Rem. useful life (yrs.): 0008 41f. Cost to reconstruct/replace: \$0.00 \_\_\_\_\_

41g. Comments: \_\_\_\_\_

**Other Site Features**

Pavement (Roadways / Parking Lots):

42a. Concrete  Asphalt  Gravel  Other  None

42b. Condition: Satisfactory 42c. Year of last reconstruct/replace: 2006 \_\_\_\_\_

42d. Rem. useful life (yrs.): 0009 42e. Cost to reconstruct/replace: \$0.00 \_\_\_\_\_

42f. Comments: \_\_\_\_\_

Sidewalks:

43a. Concrete  Asphalt  Other

43b. Condition: Satisfactory 43c. Year of last reconstruct/replace: 2005 \_\_\_\_\_

43d. Rem. useful life (yrs.): 0016 43e. Cost to reconstruct/replace: \$0.00 \_\_\_\_\_

43f. Comments: \_\_\_\_\_

Playgrounds and Equipment:

44a. Condition: N/A 44b. Year of last reconstruct/replace: \_\_\_\_\_

44c. Rem. useful life (yrs.): \_\_\_\_\_ 44d. Cost to reconstruct/replace: \$0.00 \_\_\_\_\_

44e. Comments: \_\_\_\_\_

Athletic Fields, Play Fields and Related Structures:

45a. Condition: Satisfactory 45b. Year of last reconstruct/replace: 2005 \_\_\_\_\_

45c. Rem. useful life (yrs.): 0008 45d. Cost to reconstruct/replace: \$0.00 \_\_\_\_\_

45e. Comments: \_\_\_\_\_

**Substructure**

46a. Reinforced concrete  Masonry on concrete footing  Other

46b. Evidence of structural concerns:

46b1. Structural cracks  46b2. Heaving/Jacking  46b3. Decay/Corrosion

46b4. Water penetration  46b5. Unsupported areas  46b6. Other

46c. Condition: Satisfactory 46d. Year of last reconstruct/replace: 1999 \_\_\_\_\_

46e. Rem. useful life (yrs.): 0013 46f. Cost to reconstruct/replace: \$0.00 \_\_\_\_\_

46g. Comments: Water penetration at tunnel entr of main boiler rm \_\_\_\_\_

**Building Envelope**

Structural Floors:

- 47a1. Reinforced Concrete slab on Grade  47a4. Wood Deck on Wood Trusses
- 47a2. Concrete/Metal Deck/Metal Joist  47a5. Wood Deck on Wood Joists
- 47a3. Precast Concrete Structural System  47a6. Concrete Deck on Wood Structure
- 47a7. Other: \_\_\_\_\_

47b. Evidence of structural concerns with Beams/Joists/Trusses/Etc.:

- 47b1. Structural cracks  47b4. Deflection
- 47b2. Unsupported End  47b5. Seriously Damaged/Missing Components
- 47b3. Rot/Decay/Corrosion  47b6. Other Problems \_\_\_\_\_

47c. Evidence of structural concerns with structural floor deck:

- 47c1. Cracks  47c2. Deflection  47c3. Rot/Decay/Corrosion

47d. Condition: Satisfactory 47e. Year of last reconstruct/replace: 1999

47f. Rem. useful life (yrs.): 0007 47g. Cost to reconstruct/replace: \$0.00

47h. Comments: \_\_\_\_\_

Exterior Walls / Columns:

- 48a. Concrete  Masonry  Steel  Wood  Other

48b. Evidence of structural concerns with Columns/Base Plates/Connections/Etc.:

- 48b1. Structural cracks  48b2. Rot/Decay/Corrosion  48b3. Other Problems: \_\_\_\_\_

48c. Evidence of concerns with Exterior Cladding:

- 48c1. Cracks/Gaps  48c4. Moisture Penetration
- 48c2. Inadequate Flashing  48c5. Rot/Decay/Corrosion
- 48c3. Efflorescence  48c6. Other Problems: \_\_\_\_\_

48d. Condition: Satisfactory 48e. Year of last reconstruct/replace: 1999

48f. Rem. useful life (yrs.): 0016 48g. Cost to reconstruct/replace: \$0.00

48h. Comments: \_\_\_\_\_

Chimneys:

- 49a. Masonry  Concrete  Metal  Other  N/A

49b. Condition: Satisfactory 49c. Year of last reconstruct/replace: 1956

49d. Rem. useful life (yrs.): 0010 49e. Cost to reconstruct/replace: \$0.00

49f. Comments: \_\_\_\_\_

Parapets:

- 50a. Masonry  Concrete  Metal  Other  N/A

50b. Condition: \_\_\_\_\_ 50c. Year of last reconstruct/replace: \_\_\_\_\_

50d. Rem. useful life (yrs.): \_\_\_\_\_ 50e. Cost to reconstruct/replace: \$0.00

50f. Comments: \_\_\_\_\_

Exterior Doors:

51a. Condition of Exterior Doors: Satisfactory 51b. Condition of Ext. Door Hdw: Satisfactory  
 51c. Exit doors have magnetic locking devices? 51d. Safety/Security features are adequate?: Yes  
51e. Year of last reconstruct/replace: 1999 51f. Rem. useful life (yrs.): 0008  
51g. Cost to reconstruct/replace: \$0.00 51h. Comments: \_\_\_\_\_

Exterior Steps, Stairs, and Ramps:

52a. Condition: Satisfactory 52b. Year of last reconstruct/replace: 2006  
52c. Rem. useful life (yrs.): 0014 52d. Cost to reconstruct/replace: \$0.00  
52e. Comments: \_\_\_\_\_

Fire Escapes:

53a. Does the building have 1 or more fire escapes 53b. Condition: N/A  
 53c. Safety features are adequate? 53d. Year of last reconstruct/replace: \_\_\_\_\_  
53e. Rem. useful life (yrs.): \_\_\_\_\_ 53f. Cost to reconstruct/replace: \$0.00  
53g. Comments: \_\_\_\_\_

Windows:

54a. Aluminum  Steel  Vinyl  Solid Wood  Wood w/ Ext. Cladding  Other  
54b. Condition: Satisfactory 54c. All rescue windows are operable?: Yes  
54d. Year of last reconstruct/replace: 2001 54e. Rem. useful life (yrs.): 0016  
54f. Cost to reconstruct/replace: \$50,000.00 54g. Comments: Replace blinds as needed

Roof & Skylights:

55a. Type of roof construction:  
 55a1. Metal deck on metal trusses / joists  55a4. Concrete on metal deck on metal trusses / joist  
 55a2. Wood deck on wood trusses / joists  55a5. Other: \_\_\_\_\_  
 55a3. Wood deck on metal trusses / joists

55b. Type of roofing material:  
 55b1. Single ply membrane  55b4. Pre-formed metal  55b7. Other: \_\_\_\_\_  
 55b2. Built-up  55b5. IRMA  
 55b3. Asphalt single  55b6. Slate

55c. Evidence of structural concerns with beams/joists/trusses/etc.:  
 55c1. Structural cracks  55c4. Deflection  
 55c2. Unsupported ends  55c5. Seriously damaged / missing components  
 55c3. Rot/Decay/Corrosion 55c6. Other Problems: \_\_\_\_\_

55d. Evidence of structural concerns with structural floor deck:  
 55d1. Cracks  55d2. Deflection  55d3. Rot/Decay/Corrosion  
 55e. Does the building have skylights?  
55f. If yes, what material are the skylights made of?: Plastic

55g. Condition: Satisfactory

55h. Evidence of concerns with roofing, skylights, flashing and drains:

55h1. Failures/Splits/Cracks?: No 55h4. Poorly func. roof drains?: Yes  
55h2. Rot/Decay/Corrosion?: No 55h5. Evidence of water pen.?: Yes  
55h3. Inad. Flashing/curbs/pitch?: No 55h6. Other Concerns: No

55i. Condition: Satisfactory 55j. Year of last reconstruct/replace: 1999  
55k. Rem. useful life (yrs.): 0002 55l. Cost to reconstruct/replace: \$15,000.00  
55m. Comments: Additional roof drains needed

### Interior Spaces

#### Interior Bearing Walls & Fire Walls:

56a. Condition: Satisfactory 56b. Year of last reconstruct/replace: 1999  
56c. Rem. useful life (yrs.): 0016 56d. Cost to reconstruct/replace: \$0.00  
56e. Comments: \_\_\_\_\_

#### Other Interior Walls:

57a. Condition: Satisfactory 57b. Year of last reconstruct/replace: 2004  
57c. Rem. useful life (yrs.): 0016 57d. Cost to reconstruct/replace: \$0.00  
57e. Comments: \_\_\_\_\_

#### Floor Finishes:

58a. Type of floor finishes in instructional spaces:

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> 58a1. Carpet                            | <input checked="" type="checkbox"/> 58a4. Hard flooring |
| <input checked="" type="checkbox"/> 58a2. Resilient tiles or sheet flooring | <input type="checkbox"/> 58a5. Other                    |
| <input checked="" type="checkbox"/> 58a3. Wood                              | <input type="checkbox"/> 58a6. N/A                      |

58b. Type of floor finishes in common areas:

- |   |   |
|---|---|
| <input checked="" type="checkbox"/> 58b1. Carpet                            | <input checked="" type="checkbox"/> 58b4. Hard flooring |
| <input checked="" type="checkbox"/> 58b2. Resilient tiles or sheet flooring | <input type="checkbox"/> 58b5. Other                    |
| <input checked="" type="checkbox"/> 58b3. Wood                              | <input type="checkbox"/> 58b6. N/A                      |

58c. Condition: Satisfactory 58d. Year of last reconstruct/replace: 2005  
58e. Rem. useful life (yrs.): 0008 58f. Cost to reconstruct/replace: \$100,000.00  
58g. Comments: Repair/replace inside terrazo

#### Ceilings:

59a. Condition: Satisfactory 59b. Year of last reconstruct/replace: 2001  
59c. Rem. useful life (yrs.): 0008 59d. Cost to reconstruct/replace: \$0.00  
59e. Comments: \_\_\_\_\_

Other Interior Walls/Lockers:

60a. Condition of Wall Units: Satisfactory 60b. Year of last reconstruct/replace: 1999  
60c. Rem. useful life (yrs.): 0002 60d. Cost to reconstruct/replace: \$208,000.00  
60e. Comments: Replace lockers & gym bleachers

Interior Doors:

61a. Condition of int. door units: Satisfactory 61b. Condition of int. door hardware: Satisfactory  
61c. Year of last reconstruct/replace: 1999 61d. Rem. useful life (yrs.): 0007  
61e. Cost to reconstruct/replace: \$0.00 61f. Comments: \_\_\_\_\_

Interior Stairs:

62a. Condition: Satisfactory 62b. Year of last reconstruct/replace: 1999  
62c. Rem. useful life (yrs.): 0016 62d. Cost to reconstruct/replace: \$0.00  
62e. Comments: \_\_\_\_\_

Elevators, Lifts and Escalators:

63a. Condition: Satisfactory 63b. Year of last reconstruct/replace: 1999  
63c. Rem. useful life (yrs.): 0003 63d. Cost to reconstruct/replace: \$0.00  
63e. Comments: \_\_\_\_\_

Interior Electrical Dist.:

Interior electrical supply meets current needs?

64b. Condition: Satisfactory 64c. Year of last reconstruct/replace: 2002  
64d. Rem. useful life (yrs.): 0006 64e. Cost to reconstruct/replace: \$0.00  
64f. Comments: \_\_\_\_\_

Lighting Fixtures:

65a. Condition: Satisfactory 65b. Year of last reconstruct/replace: 2006  
65c. Rem. useful life (yrs.): 0009 65d. Cost to reconstruct/replace: \$0.00  
65e. Comments: \_\_\_\_\_

Communication Systems:

66a. Systems adequate?: Yes  
66b. Condition: Excellent 66c. Year of last reconstruct/replace: 2007  
66d. Rem. useful life (yrs.): 0010 66e. Cost to reconstruct/replace: \$0.00  
66f. Comments: \_\_\_\_\_

Swimming Pool and Systems:

67a. Condition: N/A 67b. Year of last reconstruct/replace: \_\_\_\_\_  
67c. Rem. useful life (yrs.): \_\_\_\_\_ 67d. Cost to reconstruct/replace: \$0.00  
67e. Comments: \_\_\_\_\_

**Plumbing (Excluding HVAC)**

Water Dist. Systems:

68a. Iron  Galvanized  Copper  Lead  PVC  Other  N/A  
68b. Condition: Satisfactory 68c. Year of last reconstruct/replace: 1999  
68d. Rem. useful life (yrs.): 0006 68e. Cost to reconstruct/replace: \$0.00  
68f. Comments: \_\_\_\_\_

Plumbing Drainage System:

69a. Iron     Galvanized     Copper     Lead     PVC     Other     N/A  
69b. Condition: Satisfactory    69c. Year of last reconstruct/replace: 2001  
69d. Rem. useful life (yrs.): 0007    69e. Cost to reconstruct/replace:    \$0.00  
69f. Comments: \_\_\_\_\_

Hot Water Heaters:

70a. Oil     Natural Gas     Electricity     Other     N/A  
70b. Condition: Satisfactory    70c. Year of last reconstruct/replace: 2005  
70d. Rem. useful life (yrs.): 0013    70e. Cost to reconstruct/replace:    \$3,500.00  
70f. Comments: Add in kitchen

Plumbing Fixtures:

71a. Condition: Satisfactory    71b. Year of last reconstruct/replace: 1999  
71c. Rem. useful life (yrs.): 0008    71d. Cost to reconstruct/replace:    \$199,000.00  
71e. Comments: Replace partitions for ADA

**HVAC Systems**

HVAC System Type:

72a. Central HVAC system?  
 72b. Constant Volume     Variable Air Volume     DualDuct / Multizone     Other

Heat Generating Systems:

73a. Boiler / Hot Water     Boiler / Steam     Furnace / Forced Air     Other  
73b. Condition: Satisfactory    73c. Year of last reconstruct/replace: 2005  
73d. Rem. useful life (yrs.): 0013    73e. Cost to reconstruct/replace:    \$0.00  
73f. Comments: \_\_\_\_\_

Heating Fuel / Energy Systems:

74a. Condition: Satisfactory    74b. Year of last reconstruct/replace: 1999  
74c. Rem. useful life (yrs.): 0008    74d. Cost to reconstruct/replace:    \$0.00  
74e. Comments: \_\_\_\_\_

Cooling / AC Generating Systems:

75a. Condition: Satisfactory    75b. Year of last reconstruct/replace: 1999  
75c. Rem. useful life (yrs.): 0006    75d. Cost to reconstruct/replace:    \$0.00  
75e. Comments: \_\_\_\_\_

Air Handling and Ventilation Equipment:

76a. Condition: Satisfactory    76b. Year of last reconstruct/replace: 1968  
76c. Rem. useful life (yrs.): 0004    76d. Cost to reconstruct/replace:    \$130,000.00  
76e. Comments: Equip w/pre-filters & HEPA filters/upgrade in gym

Piped Heating and Cooling Dist. Systems:

77a. Condition: Satisfactory    77b. Year of last reconstruct/replace: 1988  
77c. Rem. useful life (yrs.): 0006    77d. Cost to reconstruct/replace:    \$550,000.00

77e. Comments: Abate crawl space/replace univents

Ducted Heating and Cooling Dist. Systems:

78a. Condition: Satisfactory 78b. Year of last reconstruct/replace: 1968

78c. Rem. useful life (yrs.): 0006 78d. Cost to reconstruct/replace: \$20,000.00

78e. Comments: Clean ductwork

HVAC Control Systems:

79a. Condition: Satisfactory 79b. Year of last reconstruct/replace: 2004

79c. Rem. useful life (yrs.): 0008 79d. Cost to reconstruct/replace: \$0.00

79e. Comments: \_\_\_\_\_

**Fire Safety Systems**

Fire Alarm Systems:

80a. Condition: Satisfactory 80b. Year of last reconstruct/replace: 1999

80c. Rem. useful life (yrs.): 0007 80d. Cost to reconstruct/replace: \$0.00

80e. Comments: \_\_\_\_\_

Smoke Detection Systems:

81a. Condition: Satisfactory 81b. Year of last reconstruct/replace: 1999

81c. Rem. useful life (yrs.): 0007 81d. Cost to reconstruct/replace: \$0.00

81e. Comments: \_\_\_\_\_

Fire Supression Systems:

82a. Condition: Satisfactory 82b. Year of last reconstruct/replace: 2000

82c. Rem. useful life (yrs.): 0008 82d. Cost to reconstruct/replace: \$0.00

82e. Comments: \_\_\_\_\_

Emergency Lighting Systems:

83a. Condition: Satisfactory 83b. Year of last reconstruct/replace: 1999

83c. Rem. useful life (yrs.): 0007 83d. Cost to reconstruct/replace: \$0.00

83e. Comments: \_\_\_\_\_

Emergency Standby Power Systems:

84a. Building has an emergency or standby power system

84b. Condition: Satisfactory 84c. Year of last reconstruct/replace: 1968

84d. Rem. useful life (yrs.): 0003 84e. Cost to reconstruct/replace: \$150,000.00

84f. Comments: Replace

**Accessibility**

85. Is there an accessible exterior route for persons with disabilities?

86. Is there an accessible interior route for persons with disabilities for goods/services & restrooms?

87a. Cost of Improvements to provide accessible interior and exterior routes: \$0.00

87b. Comments: \_\_\_\_\_

**Environmental / Comfort / Health**

88a. General appearance: Good

88b. Comments: \_\_\_\_\_

89a. Cleanliness: Good

88b. Comments: \_\_\_\_\_

90a. Acoustics: Good

90b. Comments: \_\_\_\_\_

91a. Types of lighting in general purpose classrooms:

91a1. Daylight  91a4. Incandescent

91a2. Fluorescent- NOT Full Spectrum  91a5. Other

91a3. Fluorescent- Full Spectrum  91a6. N/A

91b. Overall rating: Good

91c. Comments: \_\_\_\_\_

92. Is there evidence of active infestations of:

92a. Rodents  92b. Wood Boring/Eating Insects  92c. Cockroaches  92d. Other Vermin

**Indoor Air Quality**

93. Is mold visible in or around the following areas?

93a1. Classrooms: No 93a4. Other areas: No

93a2. Common areas: No 93a4. Specify: \_\_\_\_\_

93a3. Supply/Return grills: No

93b. Est. cost for improvements: \$0.00 93c. Comments: \_\_\_\_\_

94. Humidity/moisture- Are any of the following found in or around these areas?

94a. In Classrooms 94b. In Other Areas

94ab1. Visible water damage: Yes No

94ab2. Active leaks in roof: Yes No

94ab3. Active plumbing leaks: No No

94ab4. Moisture/Condensation: No No

94c. Rating of humidity/moisture condition in building: Good

95. Ventilation: Are there fresh air intakes near the following?

95a1. Near bus loading area: No

95a2. Truck delivery areas: No

95a3. Near garbage disposal areas No

95b. Accumulated dirt, dust, debris around fresh air intakes?: No

95c. Fresh air intakes free of blockage?: Yes

95d. Accumulated dirt, dust, debris in ductwork?: Yes

95e. Dampers functioning as designed?: Yes

95f. Condition of air filters: Fair

95g. Outside air is adequate for occupant load: Unable to Determine  
95h. Rating of ventilation/indoor air quality: Unable to Determine  
95i. Comments: \_\_\_\_\_

### **Indoor Air Quality Plan**

96a. Does the school district use EPA's Tools for Schools Program? Yes  
96b. If not, is some other IAQ management plan used? \_\_\_\_\_

### **American Red Cross**

97a. Is there a written agreement with the American Red Cross for the use of this building as an emergency shelter? Yes  
97b. Does this building have an emergency generator to support sheltering operations? (lights, HVAC, etc.)? Yes

### **Contacts**

99. District Director of Facilities: John Drenckhahn  
100. Director Phone Number: 631-226-6442  
101. Health & Safety Comm. Member: Robert Cozzetto  
102. H&S Comm. Member Number: 631-884-0382  
103. Code Enf. Official: Lou Mira  
104. Registry Number: 1195-0587B