

<b>Lindenhurst UFSD</b>						
<b>Periodic Surveillance #4</b>						
<b>Harding Avenue Elementary School</b>				<b>Date:</b>	<b>July 7, 2009</b>	
<b>Inspector:</b>	<b>Thomas G. Gillen</b>			<b>Signature:</b>		
<b>Space ID</b>	<b>Material</b>	<b>Description</b>	<b>Lin. Ft.</b>	<b>Sq. Ft.</b>	<b>Room/Area</b>	<b>Changes in Condition</b>
1001	TSI	pipe	5		106	<b>NO CHANGES</b>
1002	TSI	pipe	4		107	<b>NO CHANGES</b>
1029	TSI	46 Pipe Elbows		N/A	Crawlspace below Kitchen	<b>ABATED April 2009</b>
N/A	TSI	Pipe Joints		N/A	Above Ceilings	<b>ASSUMED TO CONTAIN ACBM</b>
N/A	Misc	Electrical Wiring	N/A		AP Room Stage Area	<b>ASSUMED TO CONTAIN ACBM</b>