

2005 Building Condition Survey Instrument

1. School District: Lindenhurst 2. SED Control #: 5801040300000001
3. Building Name: Kellum School 4. SED District #: 58010403
5. Survey Inspect. Date: 7/15/2005 6. Building 911 Address: 887 Kellum St.
7. City: Lindenhurst 8. Zip: 11757 9.&10. C/O Status: CURRENT 01/14/2005

Building Age and Gross Square Footage

11. Yr. Original Building: 1964 12. Gross Sq.FT as Configured: 70800
13. Number of Floors: 1

Building Ownership and Occupancy Status

14. Building Use Status (Disposition as of 10/01/05): a.Occupied
15. Building Ownership: a.Owned
16. Purposes Building is Currently Used?:
 Student Instructional Purposes Other Purposes: _____
 District Administration Used by Other Organizations

Building Users

17. Students registered to receive instruction in this building as of 10/1/05: 400
18. Of these, how many receive most of their instruction in:
Permanent Instructional Spaces: 0 Temporary Instructional Spaces: 0
Non-instructional Spaces used as Instructional Spaces: 0
 Cafeteria Library Storage Space
 Gym Lobby Other (Describe): _____
 Admin. Spaces Stairwell
19. Grades Housed: PRE-K 20. Days Building Closed for '04-'05: 0
 21. Building used for instructional purposes in the summer?
 22. Renovations or construction during past 12 months?

Program Spaces

23. Number of General Purpose Classrooms: 35
24. Gross Sq. FT of all Gen. Purpose Classrooms: 31500