

2005 Building Condition Survey Instrument

1. School District: Lindenhurst 2. SED Control #: 5801040300000013
3. Building Name: Margaret A. McKenna Admin. 4. SED District #: 58010403
5. Survey Inspect. Date: 6/23/2005 6. Building 911 Address: 350 Daniel St.
7. City: Lindenhurst 8. Zip: 11757 9.&10. C/O Status: CURRENT 10/01/06

Building Age and Gross Square Footage

11. Yr. Original Building: 1965 12. Gross Sq.FT as Configured: 46500
13. Number of Floors: 2

Building Ownership and Occupancy Status

14. Building Use Status (Disposition as of 10/01/05): a.Occupied
15. Building Ownership: a.Owned
16. Purposes Building is Currently Used?:
 Student Instructional Purposes Other Purposes: _____
 District Administration Used by Other Organizations

Building Users

17. Students registered to receive instruction in this building as of 10/1/05: _____ 50
18. Of these, how many receive most of their instruction in:
Permanent Instructional Spaces: _____ 50 Temporary Instructional Spaces: _____ 0
Non-instructional Spaces used as Instructional Spaces: _____ 0
 Cafeteria Library Storage Space
 Gym Lobby Other (Describe): _____
 Admin. Spaces Stairwell
19. Grades Housed: 3-5, 9-12 20. Days Building Closed for '04-'05: _____ 0
 21. Building used for instructional purposes in the summer?
 22. Renovations or construction during past 12 months?

Program Spaces

23. Number of General Purpose Classrooms: _____ 25
24. Gross Sq. FT of all Gen. Purpose Classrooms: _____ 22500