

<b>Lindenhurst UFSD</b>						
<b>Periodic Surveillance #4</b>						
<b>Lindenhurst High School</b>				<b>Date:</b>	<b>July 7, 2009</b>	
<b>Inspector:</b>	<b>Thomas G. Gillen</b>			<b>Signature:</b>		
<b>Space ID</b>	<b>Material</b>	<b>Description</b>	<b>Lin.Ft.</b>	<b>Sq.Ft.</b>	<b>Room/Area</b>	<b>Changes in Condition</b>
1001	TSI	pipe	200		Crawlspace	<b>NO CHANGES</b>
2002	TSI	pipe	10		shop1	<b>NO CHANGES</b>
2007	TSI	pipe	18		shop2	<b>NO CHANGES</b>
2008	TSI	pipe	24		shop3	<b>NO CHANGES</b>
2010	TSI	pipe	9		photolab	<b>NO CHANGES</b>
2014	TSI	pipe	10		shop4	<b>NO CHANGES</b>
2015	TSI	pipe	8		shop5	<b>NO CHANGES</b>
2018	TSI	pipe	26		shop6	<b>NO CHANGES</b>
2027	TSI	pipe	15		hall-corridor H	<b>NO CHANGES</b>
2048	TSI	pipe	30		hall-corridor G	<b>NO CHANGES</b>
2068	TSI	pipe	15		hall-corridor J	<b>NO CHANGES</b>
2093	TSI	pipe	20		hall-corridor L	<b>NO CHANGES</b>
2106	TSI	pipe	30		copy room	<b>NO CHANGES</b>
2113	TSI	pipe	27		storage	<b>NO CHANGES</b>
2119	TSI	pipe	30		dishwasher	<b>NO CHANGES</b>
2200	TSI	pipe	41		hall-corridor E	<b>NO CHANGES</b>
2213	TSI	pipe	18		hall-corridor D	<b>NO CHANGES</b>
3253	TSI	pipe	20		hall-corridor N	<b>NO CHANGES</b>
3275	TSI	pipe	35		hall-corridor M	<b>NO CHANGES</b>
3291	TSI	pipe	19		hall-corridor O	<b>NO CHANGES</b>
3331	TSI	pipe	20		hall-corridor P	<b>NO CHANGES</b>
	Misc	Electrical Wiring	N/A		Throughout	<b>NO CHANGES</b>
	Misc	Soil		N/A	Crawlspace	<b>NO CHANGES</b>